



## Safety bulletin 2024-09-30

### Xstream 1<sup>st</sup> stages, from batch number 23-03 and 23-30.

It's been discovered that Xstream first stage housings marked with batch numbers 23-03 and 23-30 could have a problem with the thread to the connection pipe and this can cause the cup filter 4552 to become loose and in worst case break the cup filter when the 1<sup>st</sup> stage is pressurized.



### How can I check this?

Start with checking your 1<sup>st</sup> stages, to see if you have any of these 1<sup>st</sup> stages.

If you find 1<sup>st</sup> stages that are marked with either of these batch numbers, check the following:

- If you shake the 1<sup>st</sup> stage, can you hear the cup filter rattle?
- If you taken a thin, long and blunt tool and stick it down the connection stem, can you feel the cup filter move?

If the answer to both these questions is No, then the 1<sup>st</sup> stage is ok and can be used.

If the answer to any of these questions is Yes, then you should contact the dealer where you purchased your regulator or [support@poseidon.com](mailto:support@poseidon.com).

Västra Frölunda 2024-09-30.

Poseidon Diving Systems AB  
Beatrice Lesslies Gata 7  
421 31 Västra Frölunda  
Sweden.